



Gas Pipe Line Indonesia



Problem Definition

A condensated gas pipeline needed maintenance. It was effected by corrosion. Due to the cold gas running through the pipe and the humid environment the pipe line was constantly condensated, which made conventional paints unusefull.

Project Description

After sandblasting the pipeline, the old material and rust was removed. To tackle the condensation issue Moist Metal Grip was used as a base coat. For safety reasons the Moist Metal Grip was then coated with yellow tinted EnamoGrip. The trial was done at the pumping station. Treatment of the entire pipeline is dicussed and might proceed in 2009/2010. The results were extremely satisfying and no other products performed so well in the Tender. A big advantage was the application could be done Online. Please contact us for more information or pictures

Products

Moist Metal Grip, EnamoGrip®

Project Pictures

