



Kazakhstan PetroChemical Facility
Metal Jacket and fiberglass Removed to expose the corrosion under the insulation. Wire brush was used to clean the surface of the pipe, then HPC was sprayed over hot surface of the pipe to insulate the pipe more efficiently than the wrap and metal jacket.